



1369 N. Killian Drive, Lake Park, FL 33403

tel 561-845-7888 · fax 561-845-6777 · www.renntechmercedes.com

©Copyright 2010 Renntech, Inc. All rights reserved. Distribution of this document, including but not limited to distribution on the Internet is expressly prohibited unless approved in writing by Renntech, Inc.

Instructions for removing the TCU on R230 Chassis



1. Open the passenger-side door of the vehicle
2. Remove plastic screw cover and unscrew panel retention screw



3. Remove side kick-panel
4. Remove TCU connectors (2)
5. Remove the TCU